

## UST Service Provider List (Central)

| <b>Company</b>  | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|---|--------------------------|---|---|
| <b>Advanced Environmental Solutions, LLC</b><br>P.O. Box 1426<br>Black Mountain, NC 28711<br><br><b>Phone</b> (828) 664-9822<br><b>Fax</b> (866) 425-2661<br><br><b>Website</b> | 9/2/2015                 |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:   | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:  | No  |
| Containment Sump Testing:   | <b>Yes</b>               | Statistical Inventory Reconciliation Services:    | <b>Yes</b>  |
| Corrosion Protection Design Experts:  | No                       | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:  | No                       | Tank Tightness Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Testing:  | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:   | No                       | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:   | No                       | Other:  |   |
| Line Tightness Testing:   | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>  |                          |   |   |
| Emergency Cleanup - Spill/Release:  | No                       | UST Compliance Consultants:                       | No  |
| Environmental Engineer/Geologist - Site Checks:   | No                       | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | No                       | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:  | No                       | Other:  |   |
| Soil and Water Testing Lab:   | No                       |   |   |

| <b>Company</b>   | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|--|--------------------------|---|---|
| <b>Advanced Environmental Solutions, LLC</b><br>P.O. Box 1426<br>Black Mountain, NC 28711<br><br><b>Phone</b> (828) 664-9822<br><b>Fax</b> (866) 425-2661<br><br><b>Website</b> <a href="http://advancedenvironmentalsolutions.com">advancedenvironmentalsolutions.com</a> | #####                    |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:  | No  |
| Containment Sump Testing:  | <b>Yes</b>               | Statistical Inventory Reconciliation Services:    | <b>Yes</b>  |
| Corrosion Protection Design Experts:   | No                       | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:   | No                       | Tank Tightness Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Testing:   | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:  | No                       | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:  | No                       | Other:  |   |
| Line Tightness Testing:  | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>   |                          |   |   |
| Emergency Cleanup - Spill/Release:   | No                       | UST Compliance Consultants:                       | No  |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:   | No                       | Other:  |   |
| Soil and Water Testing Lab:  | No                       |   |   |

## UST Service Provider List (Central)

| <b>Company</b>   | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|--|--------------------------|---|---|
| <b>AES of Greenville</b><br>PO Box 59<br>Greenville, NC 27835<br><br><b>Phone</b> (252) 758-3311<br><b>Fax</b> (252) 481-5814<br><br><b>Website</b> <a href="http://www.aes-nc.com">www.aes-nc.com</a> | 8/26/2015                |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>  |
| Containment Sump Testing:  | <b>Yes</b>               | Statistical Inventory Reconciliation Services:    | <b>Yes</b>  |
| Corrosion Protection Design Experts:   | <b>Yes</b>               | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:   | <b>Yes</b>               | Tank Tightness Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Testing:   | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments): | <b>Yes</b>  |
| Leak Detection Equipment Operability Check:  | <b>Yes</b>               | UST Internal Lining Inspections:                  | <b>Yes</b>  |
| Leak Detection Monitoring Services:  | <b>Yes</b>               | Other:  |   |
| Line Tightness Testing:  | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>   |                          |   |   |
| Emergency Cleanup - Spill/Release:   | <b>Yes</b>               | UST Compliance Consultants:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:  | <b>Yes</b>               | UST Equipment Verification:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | <b>Yes</b>               | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:   | No                       | Other:  |   |
| Soil and Water Testing Lab:  | <b>Yes</b>               |   |   |
| <b>Barrett PetroWorks LLC</b><br>809 Hillsfarm St. NE<br>Lenoir, NC 28645<br><br><b>Phone</b> (828) 729-5861<br><b>Fax</b><br><br><b>Website</b>   | 12/9/2015                |   | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>  |
| Containment Sump Testing:  | <b>Yes</b>               | Statistical Inventory Reconciliation Services:    | No  |
| Corrosion Protection Design Experts:   | <b>Yes</b>               | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:   | <b>Yes</b>               | Tank Tightness Testing:                           | No  |
| Corrosion Protection System Testing:   | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:  | <b>Yes</b>               | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:  | <b>Yes</b>               | Other:  |   |
| Line Tightness Testing:  | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>   |                          |   |   |
| Emergency Cleanup - Spill/Release:   | No                       | UST Compliance Consultants:                       | No  |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:   | No                       | Other:  |   |
| Soil and Water Testing Lab:  | No                       |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 9/8/2015  | Area of state conducts work  |
|---|---|---|--|
| <b>Blue Ridge Environmental Services, Inc.</b><br>2315 Kings Rd. Ext.<br>Shelby, NC 28152<br><br><p style="text-align: center;"><b>Phone</b> (704) 482-2111<br/> <b>Fax</b> (704) 482-4335<br/><br/> <b>Website</b></p>   |   |   | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |  |
| Environmental Service Firms   |   |   |  |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: <b>Yes</b>   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |   |  |
| Company   | Listing Submitted   | 9/10/2015   | Area of state conducts work  |
| <b>Bunnell-Lammons Engineering Inc.</b><br>130 Oval Road<br>Suite 200<br>Arden, NC 28704<br><br><p style="text-align: center;"><b>Phone</b> (828) 277-0100<br/> <b>Fax</b> (828) 277-0110<br/><br/> <b>Website</b> <a href="http://www.blecorp.com">www.blecorp.com</a></p>   |   |   | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other:         |  |
| Environmental Service Firms   |   |   |  |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: <b>Yes</b><br>Soil and Water Testing Lab: <b>Yes</b>   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: <b>Yes</b><br>Other: Trust Fund Projects  |   |  |

## UST Service Provider List (Central)

| <b>Company</b>  | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|---|--------------------------|---|---|
| <b>Cape Lookout Environmental Sciences, PLLC</b><br>8005 Clear Brook Drive<br>Raleigh, NC 27615<br><br><b>Phone</b> (919) 757-7901<br><br><b>Fax</b><br><br><b>Website</b> <a href="http://CapeLookoutEnv.com">CapeLookoutEnv.com</a> |                          | 9/23/2015   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:   | No                       | Overfill Prevention Equipment Operability Check:  | Dispenser Meter Repair/Calibration:   |
| Containment Sump Testing:   | No                       | Statistical Inventory Reconciliation Services:    | Leak Detection Equipment Installation Servicing:  |
| Corrosion Protection Design Experts:  | No                       | Spill Prevention Equipment Testing:               | Spill Bucket Installation Repair:   |
| Corrosion Protection System Repairs:  | No                       | Tank Tightness Testing:                           | UST Equipment Installation - Other:   |
| Corrosion Protection System Testing:  | No                       | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair:   |
| Leak Detection Equipment Operability Check:   | No                       | UST Internal Lining Inspections:                  | UST System Installation - Complete Systems:   |
| Leak Detection Monitoring Services:   | No                       | Other:  | UST Piping/Sump Installation:   |
| Line Tightness Testing:   | No                       |   | UST System Removal:   |
|   |                          |   | Other:  |
| <b>Environmental Service Firms</b>  |                          |   |   |
| Emergency Cleanup - Spill/Release:  | <b>Yes</b>               | UST Compliance Consultants:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:   | <b>Yes</b>               | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | <b>Yes</b>               | Waste Disposal and Treatment:                     | <b>Yes</b>  |
| Oil and Solvent Recycling:  | <b>Yes</b>               | Other:  |   |
| Soil and Water Testing Lab:   | No                       |   |   |

| <b>Company</b>  | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|---|--------------------------|---|---|
| <b>Cape Lookout Environmental Sciences, PLLC</b><br>8005 Clear Brook Drive<br>Raleigh, NC 27615<br><br><b>Phone</b> (919) 757-7901<br><br><b>Fax</b><br><br><b>Website</b> <a href="http://CapeLookoutEnv.com">CapeLookoutEnv.com</a> |                          | 9/23/2015   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:   | No                       | Overfill Prevention Equipment Operability Check:  | Dispenser Meter Repair/Calibration:   |
| Containment Sump Testing:   | No                       | Statistical Inventory Reconciliation Services:    | Leak Detection Equipment Installation Servicing:  |
| Corrosion Protection Design Experts:  | No                       | Spill Prevention Equipment Testing:               | Spill Bucket Installation Repair:   |
| Corrosion Protection System Repairs:  | No                       | Tank Tightness Testing:                           | UST Equipment Installation - Other:   |
| Corrosion Protection System Testing:  | No                       | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair:   |
| Leak Detection Equipment Operability Check:   | No                       | UST Internal Lining Inspections:                  | UST System Installation - Complete Systems:   |
| Leak Detection Monitoring Services:   | No                       | Other:  | UST Piping/Sump Installation:   |
| Line Tightness Testing:   | No                       |   | UST System Removal:   |
|   |                          |   | Other:  |
| <b>Environmental Service Firms</b>  |                          |   |   |
| Emergency Cleanup - Spill/Release:  | <b>Yes</b>               | UST Compliance Consultants:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:   | <b>Yes</b>               | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | <b>Yes</b>               | Waste Disposal and Treatment:                     | <b>Yes</b>  |
| Oil and Solvent Recycling:  | <b>Yes</b>               | Other:  |   |
| Soil and Water Testing Lab:   | No                       |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   |           | Area of state conducts work   |
|---|---|-----------|---|
| <b>Cardno, Inc.</b><br>2725 E. Millbrook<br>Suite 121<br>Raleigh, NC 27604  | <b>Phone</b> (919) 871-0999<br><b>Fax</b> (919) 871-0335<br><b>Website</b> <a href="http://www.cardno.com">www.cardno.com</a>   | 9/24/2015 | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: <b>Yes</b><br>Soil and Water Testing Lab: <b>Yes</b>   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |           |   |
| Company   | Listing Submitted   |           | Area of state conducts work   |
| <b>Cedar Rock Environmental, P.C.</b><br>807 Bullard Lane<br>Graham, NC 27253   | <b>Phone</b> (336) 376-0394<br><b>Fax</b> (336) 376-0395<br><b>Website</b> <a href="http://www.cedarrockenvironmental.com">www.cedarrockenvironmental.com</a>   | #####     | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   |           |   | Area of state conducts work |
|---|---|-----------|---|-----------------------------|
| <b>C-First, Inc.</b><br>1119 Beaumont Rd.<br>Roanoke, VA 24019  | <b>Phone</b> (540) 777-9111<br><b>Fax</b> (540) 777-9112<br><br><b>Website</b> <a href="http://www.c-firstinc.com">www.c-firstinc.com</a>   | 8/27/2015 | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |                             |
| <b>Compliance Testing and Monitoring</b>  |   |           | <b>UST Equipment Service Contractors</b>  |                             |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No         | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: No        |           | Dispenser Meter Repair/Calibration: <b>Yes</b><br>Leak Detection Equipment Installation Servicing: <b>Yes</b><br>Spill Bucket Installation Repair: <b>Yes</b><br>UST Equipment Installation - Other: <b>Yes</b><br>UST Equipment Repair: <b>Yes</b><br>UST System Installation - Complete Systems: <b>Yes</b><br>UST Piping/Sump Installation: <b>Yes</b><br>UST System Removal: <b>Yes</b><br>Other: Wayne Dispensers and Verifone POS |                             |
| <b>Environmental Service Firms</b>  |   |           |   |                             |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other: No   |           |   |                             |
| <b>Charles Broadfoot &amp; Associates, Inc.</b><br>PO Box 53730<br>1827 Morganton Rd.<br>Fayetteville, NC 28305   | <b>Phone</b> (910) 574-4748<br><b>Fax</b> 253-681-05<br><br><b>Website</b> <a href="http://www.ustcomonline.com">www.ustcomonline.com</a>   | 9/9/2015  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |                             |
| <b>Compliance Testing and Monitoring</b>  |   |           | <b>UST Equipment Service Contractors</b>  |                             |
| Automatic Line Leak Detector Testing: Off<br>Containment Sump Testing: Off<br>Corrosion Protection Design Experts: Off<br>Corrosion Protection System Repairs: Off<br>Corrosion Protection System Testing: Off<br>Leak Detection Equipment Operability Check: Off<br>Leak Detection Monitoring Services: Off<br>Line Tightness Testing: Off | Overfill Prevention Equipment Operability Check: Off<br>Statistical Inventory Reconciliation Services: Off<br>Spill Prevention Equipment Testing: Off<br>Tank Tightness Testing: Off<br>UST Internal Inspections (Integrity Assessments): Off<br>UST Internal Lining Inspections: Off<br>Other: Off |           | Dispenser Meter Repair/Calibration: Off<br>Leak Detection Equipment Installation Servicing: Off<br>Spill Bucket Installation Repair: Off<br>UST Equipment Installation - Other: Off<br>UST Equipment Repair: Off<br>UST System Installation - Complete Systems: Off<br>UST Piping/Sump Installation: Off<br>UST System Removal: Off<br>Other:   |                             |
| <b>Environmental Service Firms</b>  |   |           |   |                             |
| Emergency Cleanup - Spill/Release: Off<br>Environmental Engineer/Geologist - Site Checks: Off<br>Environmental Engineer/Geologist Soil and GW Cleanu: Off<br>Oil and Solvent Recycling: Off<br>Soil and Water Testing Lab: Off  | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: Off<br>Waste Disposal and Treatment: Off<br>Other:  |           |   |                             |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 8/27/2015 | Area of state conducts work   |
|---|---|-----------|---|
| <b>Cobb Environmental &amp; Technical Services, Inc.</b><br>P. O. Box 1602, Tupelo, MS 38802<br>871 South Green Street, Tupelo, MS 38804<br>Tupelo, MS 38804  | <b>Phone</b> (662) 841-0995<br><b>Fax</b> (662) 841-0810<br><b>Website</b> <a href="http://www.cobbenv.com">www.cobbenv.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |   |           | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: <b>Yes</b><br>Leak Detection Equipment Installation Servicing: <b>Yes</b><br>Spill Bucket Installation Repair: <b>Yes</b><br>UST Equipment Installation - Other: <b>Yes</b><br>UST Equipment Repair: <b>Yes</b><br>UST System Installation - Complete Systems: <b>Yes</b><br>UST Piping/Sump Installation: <b>Yes</b><br>UST System Removal: <b>Yes</b><br>Other: |
| <b>Environmental Service Firms</b>  |   |           |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: No<br>Other:  |           |   |
| Company   | Listing Submitted   | 9/23/2015 | Area of state conducts work   |
| <b>Cohesion, Inc.</b><br>5216 Yates Mill Pond Road<br>Raleigh, NC 27606   | <b>Phone</b> (919) 233-8626<br><b>Fax</b> (919) 233-8909<br><b>Website</b> <a href="http://www.cohesion-inc.com">www.cohesion-inc.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |   |           | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No   | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:                 |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other:   |
| <b>Environmental Service Firms</b>  |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 9/23/2015   | Area of state conducts work   |
|---|---|---|---|
| <b>Cohesion, Inc.</b><br>5216 Yates Mill Pond Road<br>Raleigh, NC 27606<br><br><b>Phone</b> (919) 233-8626<br><b>Fax</b> (919) 233-8909<br><br><b>Website</b> <a href="http://www.cohesion-inc.com">www.cohesion-inc.com</a>  |   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |   |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No   | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:   | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other:   |   |
| <b>Environmental Service Firms</b>  |   |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |   |   |
| Company   | Listing Submitted   | 8/26/2015   | Area of state conducts work   |
| <b>CROMPCO, LLC</b><br>1815 Gallagher Road<br>Plymouth Meeting, PA 19462<br><br><b>Phone</b> (800) 646-3161<br><b>Fax</b> (610) 278-7621<br><br><b>Website</b> <a href="http://www.crompco.com">www.crompco.com</a>   |   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |   |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: <b>Yes</b> | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: <b>Yes</b><br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): <b>Yes</b><br>UST Internal Lining Inspections: <b>Yes</b><br>Other: | Dispenser Meter Repair/Calibration: <b>Yes</b><br>Leak Detection Equipment Installation Servicing: <b>Yes</b><br>Spill Bucket Installation Repair: <b>Yes</b><br>UST Equipment Installation - Other: <b>Yes</b><br>UST Equipment Repair: <b>Yes</b><br>UST System Installation - Complete Systems: <b>Yes</b><br>UST Piping/Sump Installation: <b>Yes</b><br>UST System Removal: <b>Yes</b><br>Other: |   |
| <b>Environmental Service Firms</b>  |   |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: No<br>Other:  |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 9/16/2015 | Area of state conducts work   |
|---|---|-----------|---|
| <b>CSM Environmental, PLLC</b><br>PO Box 99<br>Boonville, NC 27011  | <b>Phone</b> (336) 367-4145<br><b>Fax</b> (336) 367-4772<br><b>Website</b> <a href="http://www.csmenvironmental.com">www.csmenvironmental.com</a>   |           | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |
| Company   | Listing Submitted   | 9/4/2015  | Area of state conducts work   |
| <b>EMS Environmental, Inc.</b><br>117 South Hoover Road<br>Durham, NC 27703   | <b>Phone</b> (919) 596-0470<br><b>Fax</b> (919) 596-0578<br><b>Website</b> <a href="http://www.emsenv.com">www.emsenv.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: <b>Yes</b>   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |

## UST Service Provider List (Central)

| <b>Company</b>  | <b>Listing Submitted</b> #####  | <b>Area of state conducts work</b>  |
|---|---|---|
| <b>Enviro Consulting</b><br>531 Pitts School Road NW<br>Suite D<br>Concord, NC 28027<br><br><b>Phone</b> (704) 721-0101<br><b>Fax</b> (704) 721-0102<br><br><b>Website</b> <a href="http://www.envirocorp.net">www.envirocorp.net</a>   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: <b>Yes</b> | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: <b>Yes</b><br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): <b>Yes</b><br>UST Internal Lining Inspections: <b>Yes</b><br>Other: UST Lining Installation | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: <b>Yes</b><br>Spill Bucket Installation Repair: <b>Yes</b><br>UST Equipment Installation - Other: <b>Yes</b><br>UST Equipment Repair: <b>Yes</b><br>UST System Installation - Complete Systems: <b>Yes</b><br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| <b>Environmental Service Firms</b>  |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: No<br>Other:  |   |
| <b>Environmental Compliance Services of NC, PC</b><br>13504 South Point Boulevard, Unit F<br>Charlotte, NC 28273<br><br><b>Phone</b> (704) 583-2711<br><b>Fax</b> (704) 583-2744<br><br><b>Website</b> <a href="http://www.ecsconsult.com">www.ecsconsult.com</a>   | 9/10/2015   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: No                                 | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: Eclipse -Total Tank Compliance Services                                 | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other:   |
| <b>Environmental Service Firms</b>  |   |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other: SPCC, SWPP, Due Diligence, 24/7 ER Hotline   |   |

## UST Service Provider List (Central)

| <b>Company</b>  | <b>Listing Submitted</b>                                     |  | <b>Area of state conducts work</b>  |
|---|--|--|---|
| <b>EnviroTrac Ltd.</b><br>7343 West Friendly Avenue<br>Greensboro, NC 27410<br><br><b>Phone</b> (336) 763-6025<br><b>Fax</b><br><b>Website</b> <a href="http://www.envirotrac.com">www.envirotrac.com</a>                                       | 8/31/2015  |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |  |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: <b>Yes</b>  | Overfill Prevention Equipment Operability Check: <b>Yes</b>  | Dispenser Meter Repair/Calibration: <b>Yes</b> | Leak Detection Equipment Installation Servicing: <b>Yes</b>   |
| Containment Sump Testing: <b>Yes</b>  | Statistical Inventory Reconciliation Services: <b>Yes</b>    | Spill Bucket Installation Repair: <b>Yes</b>   | UST Equipment Installation - Other: <b>Yes</b>  |
| Corrosion Protection Design Experts: <b>Yes</b>   | Spill Prevention Equipment Testing: <b>Yes</b>               | UST Equipment Repair: <b>Yes</b>               | UST System Installation - Complete Systems: <b>Yes</b>  |
| Corrosion Protection System Repairs: <b>Yes</b>   | Tank Tightness Testing: <b>Yes</b>                           | UST Piping/Sump Installation: <b>Yes</b>       | UST System Removal: <b>Yes</b>  |
| Corrosion Protection System Testing: <b>Yes</b>   | UST Internal Inspections (Integrity Assessments): <b>Yes</b> | Other: <b>Yes</b>                              |   |
| Leak Detection Equipment Operability Check: <b>Yes</b>  | UST Internal Lining Inspections: <b>Yes</b>                  |  |   |
| Leak Detection Monitoring Services: <b>Yes</b>  | Other: <b>Yes</b>  |  |   |
| Line Tightness Testing: <b>Yes</b>  |  |  |   |
| <b>Environmental Service Firms</b>  |  |  |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b>   | UST Compliance Consultants: <b>Yes</b>                       |  |   |
| Environmental Engineer/Geologist - Site Checks: <b>Yes</b>  | UST Equipment Verification: <b>Yes</b>                       |  |   |
| Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b>   | Waste Disposal and Treatment: <b>Yes</b>                     |  |   |
| Oil and Solvent Recycling: <b>Yes</b>   | Other: <b>Yes</b>  |  |   |
| Soil and Water Testing Lab: <b>Yes</b>  |  |  |   |
| <b>Envirovation Geologic Consulting and Mapping, PC</b><br>PO Box 3425<br>Boone, NC 28607<br><br><b>Phone</b> (828) 406-0772<br><b>Fax</b><br><b>Website</b> <a href="http://www.envirovationconsulting.com">www.envirovationconsulting.com</a> | #####  |  | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| <b>Compliance Testing and Monitoring</b>  |  |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: <b>No</b>   | Overfill Prevention Equipment Operability Check: <b>No</b>   | Dispenser Meter Repair/Calibration: <b>No</b>  | Leak Detection Equipment Installation Servicing: <b>No</b>  |
| Containment Sump Testing: <b>No</b>   | Statistical Inventory Reconciliation Services: <b>No</b>     | Spill Bucket Installation Repair: <b>No</b>    | UST Equipment Installation - Other: <b>No</b>   |
| Corrosion Protection Design Experts: <b>No</b>  | Spill Prevention Equipment Testing: <b>No</b>                | UST Equipment Repair: <b>No</b>                | UST System Installation - Complete Systems: <b>No</b>   |
| Corrosion Protection System Repairs: <b>No</b>  | Tank Tightness Testing: <b>No</b>                            | UST Piping/Sump Installation: <b>No</b>        | UST System Removal: <b>No</b>   |
| Corrosion Protection System Testing: <b>No</b>  | UST Internal Inspections (Integrity Assessments): <b>No</b>  | Other: <b>No</b>                               |   |
| Leak Detection Equipment Operability Check: <b>No</b>   | UST Internal Lining Inspections: <b>No</b>                   |  |   |
| Leak Detection Monitoring Services: <b>No</b>   | Other: <b>No</b>   |  |   |
| Line Tightness Testing: <b>No</b>   |  |  |   |
| <b>Environmental Service Firms</b>  |  |  |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b>   | UST Compliance Consultants: <b>No</b>                        |  |   |
| Environmental Engineer/Geologist - Site Checks: <b>Yes</b>  | UST Equipment Verification: <b>No</b>                        |  |   |
| Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b>   | Waste Disposal and Treatment: <b>No</b>                      |  |   |
| Oil and Solvent Recycling: <b>No</b>  | Other: <b>No</b>   |  |   |
| Soil and Water Testing Lab: <b>No</b>   |  |  |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 8/27/2015   | Area of state conducts work   |
|---|---|---|---|
| <b>Evo Corporation</b><br>1703 Vargrave Street<br>Winston-Salem, NC 27107<br><br><b>Phone</b> (336) 725-5844<br><b>Fax</b> (336) 725-6244<br><br><b>Website</b> <a href="http://www.evocorp.net">www.evocorp.net</a>  |   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: <b>Yes</b><br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |   |   |
| Company   | Listing Submitted   | 1/8/2016  | Area of state conducts work   |
| <b>Excel Environmental Associates, PLLC</b><br>625 Huntsman Court<br>Gastonia, NC 28054<br><br><b>Phone</b> (704) 853-0800<br><b>Fax</b> (704) 853-3949<br><br><b>Website</b> <a href="http://www.excelengr.com">www.excelengr.com</a>  |   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other:         |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: No<br>Other:  |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 8/27/2015 | Area of state conducts work   |
|---|---|-----------|---|
| <b>Fourstar Petroleum</b><br>1119 Beaumont Rd.<br>Roanoke, VA 24019   | <b>Phone</b> (540) 563-1022<br><b>Fax</b> (540) 362-1802<br><b>Website</b> <a href="http://www.fourstartpetro.com">www.fourstartpetro.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: <b>Yes</b><br>Leak Detection Equipment Installation Servicing: <b>Yes</b><br>Spill Bucket Installation Repair: <b>Yes</b><br>UST Equipment Installation - Other: <b>Yes</b><br>UST Equipment Repair: <b>Yes</b><br>UST System Installation - Complete Systems: <b>Yes</b><br>UST Piping/Sump Installation: <b>Yes</b><br>UST System Removal: <b>Yes</b><br>Other: Wayne Dispensers and Verifone POS |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |
| Company   | Listing Submitted   | 9/13/2015 | Area of state conducts work   |
| <b>Galloway</b><br>6162 South Willow Drive<br>Suite 320<br>Greenwood Village, CO 80111  | <b>Phone</b> (303) 770-8884<br><b>Fax</b> (303) 770-3636<br><b>Website</b> <a href="http://www.GallowayUS.com">www.GallowayUS.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: UST System Design   |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   |           |   | Area of state conducts work |
|---|---|-----------|---|-----------------------------|
| <b>Geological Resources, Inc.</b><br>3502 Hayes Road<br>Monroe, NC 28110  | <b>Phone</b> (704) 845-4010<br><b>Fax</b> (704) 845-4012<br><br><b>Website</b> <a href="http://www.geologicalresourcesinc.com">www.geologicalresourcesinc.com</a>   | 8/28/2015 | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |                             |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |                             |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other:         |                             |
| Environmental Service Firms   |   |           |   |                             |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |                             |
| Company   | Listing Submitted   |           |   | Area of state conducts work |
| <b>HARCO Services LLC</b><br>PO Box 2347<br>Kennesaw, GA 30156  | <b>Phone</b> (770) 917-8846<br><b>Fax</b> (770) 917-0921<br><br><b>Website</b> <a href="http://www.harcoservices.com">www.harcoservices.com</a>   | 9/17/2015 | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |                             |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |                             |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: <b>Yes</b><br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |                             |
| Environmental Service Firms   |   |           |   |                             |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |                             |

## UST Service Provider List (Central)

| Company   | Listing Submitted   |   | Area of state conducts work   |
|---|---|---|---|
| <b>Highlands Environmental Solutions, Inc.</b><br>8410-D Falls of Neuse Road<br>Raleigh, NC 27615   | <b>Phone</b> (919) 848-3155<br><br><b>Fax</b> (919) 848-4265<br><br><b>Website</b> <a href="http://www.HESfast.com">www.HESfast.com</a>   | 9/11/2015   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |   |   |
| Company   | Listing Submitted   |   | Area of state conducts work   |
| <b>INENCO, Inc.</b><br>132 W. Statesville Ave.<br>Mooresville, NC 28115   | <b>Phone</b> (704) 662-8192<br><br><b>Fax</b> (704) 662-8194<br><br><b>Website</b> <a href="http://inenco.com">inenco.com</a>   | 9/18/2015   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:                 | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted  | *****   | Area of state conducts work   |
|---|--|---|---|
| <b>JGD Associates, Inc.</b><br>92 Moore Road<br>Avon Lake, Ohio 44012   | <b>Phone</b> 4409336825<br><br><b>Fax</b><br><br><b>Website</b> <a href="http://www.jgdpe.com">www.jgdpe.com</a>   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |  |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:                                      | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: | UST installation drawings   |
| <b>Environmental Service Firms</b>  |  |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:   |   |   |
| Company   | Listing Submitted  | 8/26/2015   | Area of state conducts work   |
| <b>Johnson, Spellman and Associates</b><br>350 Research Court<br>Suite 130<br>Peachtree Corners, GA 30092   | <b>Phone</b> (770) 447-4555<br><br><b>Fax</b><br><br><b>Website</b> <a href="http://www.jsace.com">www.jsace.com</a>   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |  |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: System design services - Engineering | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: | System design services - Engineering  |
| <b>Environmental Service Firms</b>  |  |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:   |   |   |

## UST Service Provider List (Central)

| <b>Company</b>  | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|---|--------------------------|---|---|
| <b>Law Petroleum, Inc.</b><br>11025 Arlington Church Road<br>Charlotte, NC 28227<br><br><b>Phone</b> (704) 573-3535<br><b>Fax</b> (704) 573-3535<br><br><b>Website</b>  | 10/5/2015                |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:   | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>  |
| Containment Sump Testing:   | <b>Yes</b>               | Statistical Inventory Reconciliation Services:    | <b>No</b>   |
| Corrosion Protection Design Experts:  | <b>No</b>                | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:  | <b>Yes</b>               | Tank Tightness Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Testing:  | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments): | <b>Yes</b>  |
| Leak Detection Equipment Operability Check:   | <b>Yes</b>               | UST Internal Lining Inspections:                  | <b>Yes</b>  |
| Leak Detection Monitoring Services:   | <b>Yes</b>               | Other:  |   |
| Line Tightness Testing:   | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>  |                          |   |   |
| Emergency Cleanup - Spill/Release:  | <b>Yes</b>               | UST Compliance Consultants:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:   | <b>No</b>                | UST Equipment Verification:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | <b>Yes</b>               | Waste Disposal and Treatment:                     | <b>No</b>   |
| Oil and Solvent Recycling:  | <b>No</b>                | Other:  |   |
| Soil and Water Testing Lab:   | <b>No</b>                |   |   |
| <b>Martin &amp; Slagle Geo Sciences, P.A.</b><br>P.O. Box 1023<br>24 Lookout Terrace<br>Black Mountain, NC 28711<br><br><b>Phone</b> (828) 669-3929<br><b>Fax</b> (828) 669-5289<br><br><b>Website</b> <a href="http://martinandslagle.com">martinandslagle.com</a> | 10/1/2015                |   | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| <b>Compliance Testing and Monitoring</b>  |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:   | <b>No</b>                | Overfill Prevention Equipment Operability Check:  | <b>No</b>   |
| Containment Sump Testing:   | <b>No</b>                | Statistical Inventory Reconciliation Services:    | <b>No</b>   |
| Corrosion Protection Design Experts:  | <b>No</b>                | Spill Prevention Equipment Testing:               | <b>No</b>   |
| Corrosion Protection System Repairs:  | <b>No</b>                | Tank Tightness Testing:                           | <b>No</b>   |
| Corrosion Protection System Testing:  | <b>No</b>                | UST Internal Inspections (Integrity Assessments): | <b>No</b>   |
| Leak Detection Equipment Operability Check:   | <b>No</b>                | UST Internal Lining Inspections:                  | <b>No</b>   |
| Leak Detection Monitoring Services:   | <b>No</b>                | Other:  |   |
| Line Tightness Testing:   | <b>No</b>                |   |   |
| <b>Environmental Service Firms</b>  |                          |   |   |
| Emergency Cleanup - Spill/Release:  | <b>No</b>                | UST Compliance Consultants:                       | <b>No</b>   |
| Environmental Engineer/Geologist - Site Checks:   | <b>Yes</b>               | UST Equipment Verification:                       | <b>No</b>   |
| Environmental Engineer/Geologist Soil and GW Cleanu   | <b>Yes</b>               | Waste Disposal and Treatment:                     | <b>No</b>   |
| Oil and Solvent Recycling:  | <b>No</b>                | Other:  |   |
| Soil and Water Testing Lab:   | <b>No</b>                |   |   |

## UST Service Provider List (Central)

| <b>Company</b>   | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>   |
|--|--------------------------|---|--|
| <b>MECO, Inc. of Florence</b><br>316 Raymond Street<br>Fayetteville, NC 28301<br><br><b>Phone</b> (910) 223-0020<br><b>Fax</b> (910) 223-0022<br><br><b>Website</b> <a href="http://www.mecoflorence.com">www.mecoflorence.com</a> | 9/4/2015                 |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>   |
| Automatic Line Leak Detector Testing:  | No                       | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>   |
| Containment Sump Testing:  | No                       | Statistical Inventory Reconciliation Services:    | No   |
| Corrosion Protection Design Experts:   | No                       | Spill Prevention Equipment Testing:               | No   |
| Corrosion Protection System Repairs:   | No                       | Tank Tightness Testing:                           | No   |
| Corrosion Protection System Testing:   | No                       | UST Internal Inspections (Integrity Assessments): | No   |
| Leak Detection Equipment Operability Check:  | <b>Yes</b>               | UST Internal Lining Inspections:                  | No   |
| Leak Detection Monitoring Services:  | <b>Yes</b>               | Other:  |  |
| Line Tightness Testing:  | No                       |   |  |
| <b>Environmental Service Firms</b>   |                          |   |  |
| Emergency Cleanup - Spill/Release:   | No                       | UST Compliance Consultants:                       | No   |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | No   |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | No   |
| Oil and Solvent Recycling:   | No                       | Other:  |  |
| Soil and Water Testing Lab:  | No                       |   |  |

| <b>Company</b>   | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|--|--------------------------|---|---|
| <b>National Tank Monitor, Inc.</b><br>P.O. Box 940<br>Vilonia, AR 72173<br><br><b>Phone</b> (800) 643-8265<br><b>Fax</b> (501) 796-3981<br><br><b>Website</b> <a href="http://www.nationaltankmonitor.com">www.nationaltankmonitor.com</a> | 9/29/2015                |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>  |
| Containment Sump Testing:  | <b>Yes</b>               | Statistical Inventory Reconciliation Services:    | <b>Yes</b>  |
| Corrosion Protection Design Experts:   | No                       | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:   | No                       | Tank Tightness Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Testing:   | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:  | <b>Yes</b>               | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:  | <b>Yes</b>               | Other:  |   |
| Line Tightness Testing:  | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>   |                          |   |   |
| Emergency Cleanup - Spill/Release:   | No                       | UST Compliance Consultants:                       | No  |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:   | No                       | Other:  |   |
| Soil and Water Testing Lab:  | No                       |   |   |

## UST Service Provider List (Central)

| <b>Company</b>   | <b>Listing Submitted</b>  |  | <b>Area of state conducts work</b>  |
|--|---|--|---|
| <b>Nationwide Construction Group</b><br>53861 Gratiot Ave<br>Chesterfield, MI 48051        | <b>Phone</b> (810) 533-2416<br><br><b>Fax</b><br><br><b>Website</b>   | 8/26/2015  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>   |   |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | <b>Yes</b>  | Overfill Prevention Equipment Operability Check:           | <b>Yes</b>  |
| Containment Sump Testing:  | <b>Yes</b>  | Statistical Inventory Reconciliation Services:             | <b>Yes</b>  |
| Corrosion Protection Design Experts:   | <b>Yes</b>  | Spill Prevention Equipment Testing:                        | <b>Yes</b>  |
| Corrosion Protection System Repairs:   | <b>Yes</b>  | Tank Tightness Testing:                                    | <b>Yes</b>  |
| Corrosion Protection System Testing:   | <b>Yes</b>  | UST Internal Inspections (Integrity Assessments):          | <b>Yes</b>  |
| Leak Detection Equipment Operability Check:  | <b>Yes</b>  | UST Internal Lining Inspections:                           | <b>Yes</b>  |
| Leak Detection Monitoring Services:  | <b>Yes</b>  | Other: General Contracting & New Fuel Station Construction |   |
| Line Tightness Testing:  | <b>Yes</b>  |  |   |
| <b>Environmental Service Firms</b>   |   |  |   |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                                | No  |
| Environmental Engineer/Geologist - Site Checks:  | No  | UST Equipment Verification:                                | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No  | Waste Disposal and Treatment:                              | No  |
| Oil and Solvent Recycling:   | No  | Other:   |   |
| Soil and Water Testing Lab:  | No  |  |   |
| <b>NC PETROLEUM &amp; CONVENIENCE MARKETERS</b><br>7300 GLENWOOD AVE.<br>RALEIGH, NC 27612 | <b>Phone</b> (919) 782-4411<br><br><b>Fax</b> (919) 872-4414<br><br><b>Website</b> <a href="http://WWW.NCPCM.ORG">WWW.NCPCM.ORG</a> | 8/27/2015  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>   |   |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:           | No  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:             | No  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:                        | No  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:                                    | No  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):          | No  |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:                           | No  |
| Leak Detection Monitoring Services:  | No  | Other:   |   |
| Line Tightness Testing:  | No  |  |   |
| <b>Environmental Service Firms</b>   |   |  |   |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                                | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:  | No  | UST Equipment Verification:                                | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No  | Waste Disposal and Treatment:                              | No  |
| Oil and Solvent Recycling:   | No  | Other: UST ENGINEERING                                     |   |
| Soil and Water Testing Lab:  | No  |  |   |

## UST Service Provider List (Central)

| <b>Company</b>  | <b>Listing Submitted</b> ##### |   |  |  | <b>Area of state conducts work</b>  |
|---|--------------------------------|---|--|--|---|
| <b>Nova Consulting Group, Inc.</b><br>442 South Main Street<br>Suite # 7<br>Davidson, NC 28036          |                                | <b>Phone</b> (704) 258-5196<br><br><b>Fax</b><br><br><b>Website</b> <a href="http://novaconsulting.com/">http://novaconsulting.com/</a>                     |  |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                                |   | <b>UST Equipment Service Contractors</b> |  |   |
| Automatic Line Leak Detector Testing:   | No                             | Overfill Prevention Equipment Operability Check:  | No                                       | Dispenser Meter Repair/Calibration:              | No  |
| Containment Sump Testing:   | No                             | Statistical Inventory Reconciliation Services:  | No                                       | Leak Detection Equipment Installation Servicing: | No  |
| Corrosion Protection Design Experts:  | No                             | Spill Prevention Equipment Testing:   | No                                       | Spill Bucket Installation Repair:                | No  |
| Corrosion Protection System Repairs:  | No                             | Tank Tightness Testing:   | No                                       | UST Equipment Installation - Other:              | No  |
| Corrosion Protection System Testing:  | No                             | UST Internal Inspections (Integrity Assessments):   | No                                       | UST Equipment Repair:                            | No  |
| Leak Detection Equipment Operability Check:   | No                             | UST Internal Lining Inspections:  | No                                       | UST System Installation - Complete Systems:      | No  |
| Leak Detection Monitoring Services:   | No                             | Other:  |  | UST Piping/Sump Installation:                    | No  |
| Line Tightness Testing:   | No                             |   |  | UST System Removal:                              | No  |
| <b>Environmental Service Firms</b>  |                                |   | <b>Other:</b>                            |  |   |
| Emergency Cleanup - Spill/Release:  | No                             | UST Compliance Consultants:   | <b>Yes</b>                               |  |   |
| Environmental Engineer/Geologist - Site Checks:   | <b>Yes</b>                     | UST Equipment Verification:   | No                                       |  |   |
| Environmental Engineer/Geologist Soil and GW Cleanu   | <b>Yes</b>                     | Waste Disposal and Treatment:   | No                                       |  |   |
| Oil and Solvent Recycling:  | No                             | Other:  |  |  |   |
| Soil and Water Testing Lab:   | No                             |   |  |  |   |
| <b>Petroleum Equipment and Service, Inc.</b><br>4125 Sinclair Street<br>PO Box 1949<br>Denver, NC 28037 |                                | <b>Phone</b> (704) 335-8801<br><br><b>Fax</b> (704) 342-1672<br><br><b>Website</b> <a href="http://www.petrolemequipment.net">www.petrolemequipment.net</a> |  |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                                |   | <b>UST Equipment Service Contractors</b> |  |   |
| Automatic Line Leak Detector Testing:   | <b>Yes</b>                     | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>                               | Dispenser Meter Repair/Calibration:              | <b>Yes</b>  |
| Containment Sump Testing:   | <b>Yes</b>                     | Statistical Inventory Reconciliation Services:  | No                                       | Leak Detection Equipment Installation Servicing: | <b>Yes</b>  |
| Corrosion Protection Design Experts:  | No                             | Spill Prevention Equipment Testing:   | <b>Yes</b>                               | Spill Bucket Installation Repair:                | <b>Yes</b>  |
| Corrosion Protection System Repairs:  | No                             | Tank Tightness Testing:   | <b>Yes</b>                               | UST Equipment Installation - Other:              | <b>Yes</b>  |
| Corrosion Protection System Testing:  | No                             | UST Internal Inspections (Integrity Assessments):   | No                                       | UST Equipment Repair:                            | <b>Yes</b>  |
| Leak Detection Equipment Operability Check:   | <b>Yes</b>                     | UST Internal Lining Inspections:  | No                                       | UST System Installation - Complete Systems:      | <b>Yes</b>  |
| Leak Detection Monitoring Services:   | <b>Yes</b>                     | Other:  |  | UST Piping/Sump Installation:                    | <b>Yes</b>  |
| Line Tightness Testing:   | <b>Yes</b>                     |   |  | UST System Removal:                              | <b>Yes</b>  |
| <b>Environmental Service Firms</b>  |                                |   | <b>Other:</b>                            |  |   |
| Emergency Cleanup - Spill/Release:  | No                             | UST Compliance Consultants:   | No                                       |  |   |
| Environmental Engineer/Geologist - Site Checks:   | No                             | UST Equipment Verification:   | No                                       |  |   |
| Environmental Engineer/Geologist Soil and GW Cleanu   | No                             | Waste Disposal and Treatment:   | No                                       |  |   |
| Oil and Solvent Recycling:  | No                             | Other:  |  |  |   |
| Soil and Water Testing Lab:   | No                             |   |  |  |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   |   | Area of state conducts work   |
|---|---|---|---|
| <b>Petroleum Service &amp; Calibration, Inc.</b><br>7973 Vista View Drive<br>Sherrills Ford, NC 28673   | <b>Phone</b> (704) 489-1671<br><b>Fax</b> (704) 489-1672<br><b>Website</b> <a href="http://www.petroleumtanktesting.com">www.petroleumtanktesting.com</a>   | 9/1/2015  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No  |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: <b>Yes</b>         | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: <b>Yes</b><br>Leak Detection Equipment Installation Servicing: <b>Yes</b><br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other:         |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |   |   |
| Company   | Listing Submitted   |   | Area of state conducts work   |
| <b>PGP Services, LLC</b><br>1949 Candlewick Drive<br>Fort Mill, SC 29715  | <b>Phone</b> (704) 619-1528<br><b>Fax</b> (803) 802-2441<br><b>Website</b>  | 9/2/2015  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: <b>Yes</b> | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:         | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: <b>Yes</b><br>UST Equipment Installation - Other: <b>Yes</b><br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: No<br>Other:  |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 8/26/2015   |  | Area of state conducts work   |
|---|---|---|--|---|
| <b>Pinnacle Environmental Management Support, Inc.</b><br>1100 Park Central Boulevard South, Suite 3600<br>Pompano Beach, FL 33064<br><br><b>Phone</b> (954) 977-3775<br><b>Fax</b> (866) 209-4401<br><br><b>Website</b> <a href="http://www.pinnacleems.com">www.pinnacleems.com</a>   |   |   |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   |  | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other:         |  |   |
| Environmental Service Firms   |   |   |  |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other: Trust Fund Claims Preparation & Mgmt   |   |  |   |
| Company   | Listing Submitted   | 10/5/2015   |  | Area of state conducts work   |
| <b>Practical Environmental Solutions, PC</b><br>PO Box 12590<br>Wilmington, NC 28405<br><br><b>Phone</b> (910) 790-8265<br><b>Fax</b> (866) 411-8265<br><br><b>Website</b> <a href="http://www.oil-tank.com">www.oil-tank.com</a>   |   |   |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No  |
| Compliance Testing and Monitoring   |   |   |  | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |  |   |
| Environmental Service Firms   |   |   |  |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |   |  |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 9/28/2015 | Area of state conducts work   |
|---|---|-----------|---|
| <b>Precision Tank Service</b><br>P.O. Box 2040<br>20468 Chartwell Center Dr<br>Cornelius, NC 28031  | <b>Phone</b> (704) 892-8600<br><b>Fax</b> (704) 892-8711<br><b>Website</b> <a href="http://precisiontankservice.com">precisiontankservice.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: <b>Yes</b> | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: <b>Yes</b><br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: <b>Yes</b><br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |
| Company   | Listing Submitted   | 10/5/2015 | Area of state conducts work   |
| <b>Progress Environmental, Inc.</b><br>120 Fayette Street<br>Winston-Salem, NC 27101  | <b>Phone</b> (336) 722-9999<br><b>Fax</b> (336) 722-9998<br><b>Website</b> <a href="http://www.progressenvironmental.com">www.progressenvironmental.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No   | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:                                 |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: <b>Yes</b><br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |           |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 9/2/2015  | Area of state conducts work   |
|---|---|---|---|
| <b>Protective Technologies, Inc.</b><br>711 Mill Street<br>Camden, SC 29020<br><br><b>Phone</b> (803) 424-0412<br><b>Fax</b> (803) 424-0414<br><br><b>Website</b> <a href="http://www.protectivetechnologiesinc.com">www.protectivetechnologiesinc.com</a>  |   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): <b>Yes</b><br>UST Internal Lining Inspections: <b>Yes</b><br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |   |   |
| Company   | Listing Submitted   | 9/15/2015   | Area of state conducts work   |
| <b>Pyramid Environmental &amp; Engineering PC</b><br>503 Industrial Ave<br>Greensboro, NC 27406<br><br><b>Phone</b> (336) 335-3174<br><b>Fax</b> (336) 691-0648<br><br><b>Website</b> <a href="http://www.pyramidenvironmental.com">www.pyramidenvironmental.com</a>  |   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No                                 | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:                 | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 8/26/2015 | Area of state conducts work   |
|---|---|-----------|---|
| <b>RES, Inc</b><br>PO Box 402<br>3593 Wild Cat Road<br>Williamston, NC 27892  | <b>Phone</b> (252) 809-3608<br><br><b>Fax</b><br><br><b>Website</b>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No  |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |           |   |
| Company   | Listing Submitted   | 9/8/2015  | Area of state conducts work   |
| <b>Royster Oil Company, Inc.</b><br>PO Box 1467<br>720 S Lafayette St<br>Shelby, NC 28150   | <b>Phone</b> (704) 487-6344<br><br><b>Fax</b> (704) 487-7811<br><br><b>Website</b> <a href="http://www.roysteroil.com">www.roysteroil.com</a>   |           | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   |   | Area of state conducts work   |
|---|---|---|---|
| <b>S&amp;ME, Inc.</b><br>9751 Southern Pine Blvd<br>Charlotte, NC 28273   | <b>Phone</b> 7045234723<br><br><b>Fax</b> 7045253953<br><br><b>Website</b> <a href="http://www.smeinc.com">www.smeinc.com</a>   | 10/1/2015   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |   |   |
| Company   | Listing Submitted   |   | Area of state conducts work   |
| <b>SENSIBLE SOLUTIONS ENVIRONMENTAL</b><br>PO BOX 3074<br>CHAPEL HILL, NC   | <b>Phone</b> (336) 263-0965<br><br><b>Fax</b><br><br><b>Website</b> <a href="http://www.sensible-solutions-environmental.com">www.sensible-solutions-environmental.com</a>  | 8/26/2015   | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No   |
| Compliance Testing and Monitoring   |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |   |
| Environmental Service Firms   |   |   |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |   |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted  |           | Area of state conducts work   |
|---|--|-----------|---|
| <b>Shield Engineering, Inc.</b><br>4301 Taggart Creek Road<br>Charlotte, NC 28208   | <b>Phone</b> (704) 394-6913<br><b>Fax</b> (704) 394-6968<br><b>Website</b> <a href="http://www.shieldengineering.com">www.shieldengineering.com</a>  | 10/5/2015 | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| Compliance Testing and Monitoring   |  |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:  |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |  |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:   |           |   |
| Company   | Listing Submitted  |           | Area of state conducts work   |
| <b>Simonsen Law Firm, P.C.</b><br>106 E. Queen St.<br>P.O. Box 848<br>Edenton, NC 27932   | <b>Phone</b> (252) 482-2175<br><b>Fax</b> (252) 482-1355<br><b>Website</b> <a href="http://www.simonsenlawfirm.com">www.simonsenlawfirm.com</a>  | 9/8/2015  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |  |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: Legal Services related to all UST issues |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |  |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:   |           |   |

## UST Service Provider List (Central)

| <b>Company</b>   | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>  |
|--|--------------------------|---|---|
| <b>SouthEastern Petroleum Systems, Inc.</b><br>101 Lawton Road<br>Charlotte, NC 28216<br><br><b>Phone</b> (704) 394-3178<br><b>Fax</b> (704) 394-3170<br><br><b>Website</b> <a href="http://www.sepsusa.com">www.sepsusa.com</a>                 | 8/27/2015                |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | No                       | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>  |
| Containment Sump Testing:  | <b>Yes</b>               | Statistical Inventory Reconciliation Services:    | No  |
| Corrosion Protection Design Experts:   | No                       | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:   | No                       | Tank Tightness Testing:                           | No  |
| Corrosion Protection System Testing:   | No                       | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:  | <b>Yes</b>               | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:  | No                       | Other:  |   |
| Line Tightness Testing:  | No                       |   |   |
| <b>Environmental Service Firms</b>   |                          |   |   |
| Emergency Cleanup - Spill/Release:   | No                       | UST Compliance Consultants:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:   | No                       | Other: Tank Cleaning and Biocide Treatments       |   |
| Soil and Water Testing Lab:  | No                       |   |   |
| <b>SR&amp;R Environmental, Inc.</b><br>49220 Highway 421 N.<br>PO Box 221<br>Wilmington, NC 28402<br><br><b>Phone</b> (910) 763-6274<br><b>Fax</b> (910) 763-6132<br><br><b>Website</b> <a href="http://www.srrenviro.com">www.srrenviro.com</a> | 9/22/2015                |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:  | No                       | Overfill Prevention Equipment Operability Check:  | No  |
| Containment Sump Testing:  | No                       | Statistical Inventory Reconciliation Services:    | No  |
| Corrosion Protection Design Experts:   | No                       | Spill Prevention Equipment Testing:               | No  |
| Corrosion Protection System Repairs:   | No                       | Tank Tightness Testing:                           | No  |
| Corrosion Protection System Testing:   | No                       | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:  | No                       | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:  | No                       | Other:  |   |
| Line Tightness Testing:  | No                       |   |   |
| <b>Environmental Service Firms</b>   |                          |   |   |
| Emergency Cleanup - Spill/Release:   | <b>Yes</b>               | UST Compliance Consultants:                       | No  |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | <b>Yes</b>  |
| Oil and Solvent Recycling:   | <b>Yes</b>               | Other: Vacuum Truck Service                       |   |
| Soil and Water Testing Lab:  | No                       |   |   |

## UST Service Provider List (Central)

| <b>Company</b>  | <b>Listing Submitted</b>   |  | <b>Area of state conducts work</b>  |
|---|--|--|---|
| <b>Superior Services</b><br>PO Box 982<br>Hendersonville, NC 28793<br><br><b>Phone</b> (828) 698-6286<br><b>Fax</b> (828) 698-6294<br><br><b>Website</b> <a href="http://www.superiorservices.us">www.superiorservices.us</a>   | 8/27/2015  |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |  |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: <b>Yes</b> | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): <b>Yes</b><br>UST Internal Lining Inspections: <b>Yes</b><br>Other: UST Repairs, AST inspection, testing, repair |  | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| <b>Environmental Service Firms</b>  |  |  |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:   |  |   |

| <b>Company</b>  | <b>Listing Submitted</b>  |  | <b>Area of state conducts work</b>  |
|---|---|--|---|
| <b>Terracon Consultants, Inc.</b><br>2020 Starita Road<br>Suite E<br>Charlotte, NC 28206<br><br><b>Phone</b> (704) 509-1777<br><b>Fax</b> (704) 509-1888<br><br><b>Website</b> <a href="http://www.terracon.com">www.terracon.com</a>   | 8/27/2015   |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |   |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |  | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| <b>Environmental Service Firms</b>  |   |  |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: <b>Yes</b>   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |  |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 9/3/2015 |  |  | Area of state conducts work   |
|---|---|----------|--|--|---|
| <b>Terraquest Environmental Consultants, P.C.</b><br>100 E. Ruffin Street<br>Mebane, NC 27302   | <b>Phone</b> (919) 563-9091<br><br><b>Fax</b> (919) 563-9095<br><br><b>Website</b> <a href="http://www.terraquestpc.com">www.terraquestpc.com</a>   |          |  |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |   |          |  |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |          |  |  | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other:         |
| <b>Environmental Service Firms</b>  |   |          |  |  |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  |          |  |  |   |
| Company   | Listing Submitted   | #####    |  |  | Area of state conducts work   |
| <b>The Clark Group dba Clark Environmental Services,</b><br>P.O. Box 10136<br>4918 Wrightsville Avenue<br>Wilmington, NC 28404  | <b>Phone</b> (910) 392-5555<br><br><b>Fax</b> (910) 392-5552<br><br><b>Website</b> <a href="http://www.clarkgroup.us">www.clarkgroup.us</a>   |          |  |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| <b>Compliance Testing and Monitoring</b>  |   |          |  |  | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |          |  |  | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b>Yes</b><br>Other: |
| <b>Environmental Service Firms</b>  |   |          |  |  |   |
| Emergency Cleanup - Spill/Release: <b>Yes</b><br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |          |  |  |   |

## UST Service Provider List (Central)

| Company   | Listing Submitted   | 9/9/2015 | Area of state conducts work  |
|---|---|----------|--|
| <b>The EI Group, Inc.</b><br>2101 Gateway Centre Boulevard<br>Suite 200<br>Morrisville, NC 27560  | <b>Phone</b> (919) 657-7500<br><b>Fax</b> (919) 657-7551<br><br><b>Website</b>  |          | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| Compliance Testing and Monitoring   |   |          | UST Equipment Service Contractors  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |          | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b><u>Yes</u></b><br>Other: |
| Environmental Service Firms   |   |          |  |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |          |  |
| Company   | Listing Submitted   | 9/9/2015 | Area of state conducts work  |
| <b>The EI Group, Inc.</b><br>2101 Gateway Centre Boulevard<br>Suite 200<br>Morrisville, NC 27560  | <b>Phone</b> (919) 657-7500<br><b>Fax</b> (919) 657-7551<br><br><b>Website</b>  |          | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| Compliance Testing and Monitoring   |   |          | UST Equipment Service Contractors  |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: No<br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |          | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: <b><u>Yes</u></b><br>Other: |
| Environmental Service Firms   |   |          |  |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |          |  |

## UST Service Provider List (Central)

| <b>Company</b>   | <b>Listing Submitted</b> |   | <b>Area of state conducts work</b>   |
|--|--------------------------|---|--|
| <b>TideLand Construction, LLC</b><br>1006 Wall Street<br>Greenville, NC 27858<br><br><b>Phone</b> (252) 375-8787<br><b>Fax</b> (252) 355-3932<br><br><b>Website</b> <a href="http://tidelandconstruction.com">tidelandconstruction.com</a> | 9/29/2015                |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>   |
| Automatic Line Leak Detector Testing:  | No                       | Overfill Prevention Equipment Operability Check:  | Dispenser Meter Repair/Calibration: <b>Yes</b>   |
| Containment Sump Testing:  | No                       | Statistical Inventory Reconciliation Services:    | Leak Detection Equipment Installation Servicing: <b>Yes</b>  |
| Corrosion Protection Design Experts:   | No                       | Spill Prevention Equipment Testing:               | Spill Bucket Installation Repair: <b>Yes</b>   |
| Corrosion Protection System Repairs:   | No                       | Tank Tightness Testing:                           | UST Equipment Installation - Other: <b>Yes</b>   |
| Corrosion Protection System Testing:   | No                       | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: <b>Yes</b>   |
| Leak Detection Equipment Operability Check:  | No                       | UST Internal Lining Inspections:                  | UST System Installation - Complete Systems: <b>Yes</b>   |
| Leak Detection Monitoring Services:  | No                       | Other:  | UST Piping/Sump Installation: <b>Yes</b>   |
| Line Tightness Testing:  | No                       |   | UST System Removal: <b>Yes</b>   |
| <b>Environmental Service Firms</b>   |                          |   | Other:   |
| Emergency Cleanup - Spill/Release:   | <b>Yes</b>               | UST Compliance Consultants:                       | <b>Yes</b>   |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | <b>Yes</b>   |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | <b>Yes</b>   |
| Oil and Solvent Recycling:   | No                       | Other:  |  |
| Soil and Water Testing Lab:  | No                       |   |  |
| <b>Company</b>   |                          |   | <b>Area of state conducts work</b>   |
| <b>TideLand Construction, LLC</b><br>1006 Wall Street<br>Greenville, NC 27858<br><br><b>Phone</b> (252) 375-8787<br><b>Fax</b><br><br><b>Website</b> <a href="http://tidelandconstruction.com">tidelandconstruction.com</a>                | 9/29/2015                |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No |
| <b>Compliance Testing and Monitoring</b>   |                          |   | <b>UST Equipment Service Contractors</b>   |
| Automatic Line Leak Detector Testing:  | No                       | Overfill Prevention Equipment Operability Check:  | Dispenser Meter Repair/Calibration: <b>Yes</b>   |
| Containment Sump Testing:  | No                       | Statistical Inventory Reconciliation Services:    | Leak Detection Equipment Installation Servicing: <b>Yes</b>  |
| Corrosion Protection Design Experts:   | No                       | Spill Prevention Equipment Testing:               | Spill Bucket Installation Repair: <b>Yes</b>   |
| Corrosion Protection System Repairs:   | No                       | Tank Tightness Testing:                           | UST Equipment Installation - Other: <b>Yes</b>   |
| Corrosion Protection System Testing:   | No                       | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: <b>Yes</b>   |
| Leak Detection Equipment Operability Check:  | No                       | UST Internal Lining Inspections:                  | UST System Installation - Complete Systems: <b>Yes</b>   |
| Leak Detection Monitoring Services:  | No                       | Other:  | UST Piping/Sump Installation: <b>Yes</b>   |
| Line Tightness Testing:  | No                       |   | UST System Removal: <b>Yes</b>   |
| <b>Environmental Service Firms</b>   |                          |   | Other:   |
| Emergency Cleanup - Spill/Release:   | <b>Yes</b>               | UST Compliance Consultants:                       | <b>Yes</b>   |
| Environmental Engineer/Geologist - Site Checks:  | No                       | UST Equipment Verification:                       | <b>Yes</b>   |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No                       | Waste Disposal and Treatment:                     | <b>Yes</b>   |
| Oil and Solvent Recycling:   | No                       | Other:  |  |
| Soil and Water Testing Lab:  | No                       |   |  |

## UST Service Provider List (Central)

| Company   | Listing Submitted   |          |   | Area of state conducts work |
|---|---|----------|---|-----------------------------|
| <b>UST Corrosion Management, Inc.</b><br>2764 Pleasant Rd. #10714<br>Fort Mill, SC 29708  | <b>Phone</b> (888) 822-2431<br><br><b>Fax</b> (803) 802-0561<br><br><b>Website</b> <a href="http://www.ustcorrosion.com">www.ustcorrosion.com</a>   | 9/2/2015 | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |                             |
| Compliance Testing and Monitoring   |   |          | UST Equipment Service Contractors   |                             |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |          | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |                             |
| Environmental Service Firms   |   |          |   |                             |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |          |   |                             |